	PROGRESS OF CONSTRUCTION OF T	OWERS	Phase-II	Housing	Project,	Mohali		AS ON	30.04.201	6		
Sr.		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII	Community	Guard Room	ъ
No.	Activities	A2	B5	В6	В7	C4	C5	D3	D4	Centre	1&2	Remarks
1	R.C.C Work Including Excavation,P.C.C,Raft, colmun & Slab,Machine Room and OHWT	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	UGT & PUMP Room RCC compleled
2	Brick Work in Super Structure			-	-				- Ne.VI-	-	1,0070	
i)	Brick work & lintels G.Floor	90%	95%	95%	100%	95%	100%	100%	95%	95%	100%	
ii)	Brick work & lintels 1st Floor	100%	100%	100%	100%	100%	100%	100%	100%	100%		
iii)	Brick work and lintels 2nd Floor	100%	100%	100%	100%	100%	100%	100%	100%	100%	*	
iv)	Brick work and lintels 3rd Floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
v)	Brick work and lintels 4th Floor	100%	100%	100%	100%	100%	100%	100%	100%	-	10 0 0 0	
vi)	Brick work and lintels 5th Floor	100%	100%	100%	100%	100%	100%	100%	100%			
vii)	Brick work and lintels 6th Floor	95%	100%	95%	95%	95%	100%	95%	95%	· · · ·	(* , * , * , * , * , * , * , * , * , * ,	
viii)	Brick work and lintels 7th Floor	100%	100%	100%	100%	100%	100%	100%	100%			
x)	Brick work and lintels 8th Floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
()	Brick work and lintels 9th Floor	100%	100%	100%	100%	100%	100%	100%	100%	-		- A
(i)	Brick work and lintels 10th Floor	100%	100%	100%	100%	100%	100%	100%	100%			
(ii)	Brick work and lintels 11th Floor	100%	100%	100%	100%	100%	100%	100%	100%	-		
(iii)	Brick work and lintels 12th Floor	100%	100%	100%	100%	100%	100%	100%	100%	_		
iv)	Brick work and lintels 13th Floor	Х	100%	Х	100%	100%	100%	Х	Х			
3	Internal Wall Conduit				1 4							
)	Ground Floor Internal Wall conduit	75%	80%	80%	100%	100%	100%	100%	70%	100%	100%	
)	Ist floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	100%	10070	
ii)	IInd floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	100%		
v)	IIIrd floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%			
/)	IVth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%		, a a	
/i)	Vth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%		2	
/ii)	VIth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	-		2 2
/iii).	VIIth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%		, y &	g e, no g e P
x)	VIIIth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%		k k 5	A 0 1 2 12 7
()	IXth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%			
(i)	Xth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%	•		
(ii)	XIth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%			
(iii)	XIIth floor Internal Wall conduit	100%	100%	100%	100%	100%	100%	100%	100%			
(iv)	XIIIth floor Internal Wall conduit	Х	100%	X	100%	100%	100%	X	Χ			

for MJ C-M. Saport Ass.

formature

Condeel Civil)

For Kanwarji Const. Co.

		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII		Guard Room	Remarks
Sr.		A2	B5	B6	B7	C4	C5	D3	D4	Centre	1&2	
10.	Activities	AZ			100							
4	Internal G.L.	100%	80%	80%	100%	100%	100%	100%	65%	100%	95%	
)	Ground Floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	100%		
i)	Ist floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	100%	99.75 (10.8)	
ii)	IInd floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	eny L		
v)	IIIrd floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%			
()	IVth floor Internal G.I.		100%	100%	100%	100%	100%	100%	100%			
/i)	Vth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%			
vii)	VIth floor Internal G.I.	100%		100%	100%	100%	100%	100%	100%	•		
viii)	VIIth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	1 Na 1		
ix)	VIIIth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%			3 , 3
x)	IXth floor Internal G.I.	100%	100%	100.00	100 1100 1100	100%	100%	100%	100%			
xi)	Xth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%	1 1		
xii)	XIth floor Internal G.I.	100%	100%	100%	100%	100%	100%	100%	100%			
xiii)	XIIth floor Internal G.I.	100%	100%	100%	100%	100%	100%	X	X			
xiv)	XIIIth floor Internal G.I.	X	100%	100%	100%	100%	100 /6	^	~			
5	Vertical G.I. shaft			8	4000/	80%	100%	30%	10%			
(i)	Ground Floor Vertical G.I. shaft		80%	80%	100%		100%	100%	100%	100%		
ii)	Ist floor Vertical G.I. shaft	90%	100%	100%	100%	100%	100%	100%	100%	100%		
iii)	IInd floor Vertical G.I. shaft	90%	100%	100%	100%	100%	100%	100%	100%	10070		
(iv)	IIIrd floor Vertical G.I. shaft	90%	100%	100%	100%	100%	1.4.1	100%	100%			
(v)	IVth floor Vertical G.I. shaft	90%	100%	100%	100%	100%	100%	100%	100%			
(vi)	Vth floor Vertical G.I. shaft	90%	100%	100%	100%	100%	100%	100%	100%			
(vii)		90%	100%	100%	100%	100%	100%		100%			
(viii		90%	100%	100%	100%	100%	100%	100%	100%	-		
(ix)	VIIIth floor Vertical G.I. shaft	90%	100%	100%	100%	100%	100%	100%	100%			
(x)	IXth floor Vertical G.I. shaft	90%	100%	100%	100%	100%	100%	100%				
(^) (xi)	Xth floor Vertical G.I. shaft	90%	100%	100%	100%	100%	100%	100%	100%			S
(XII		90%	100%	100%	100%	100%	100%		100%			
(xii		90%	100%	100%	100%	100%	100%		100%			
(XII		X	100%	X	100%	100%	100%	X	X			



For MIS C. M. Salve of Aft.

For Kanwarji Const. Co.

Const. Single Civil Auth. Signestory

T. E. C. Will.

_		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII	Community	Guard Room	Remarks
Sr.			B5	B6	B7	C4	C5	D3	D4	Centre	1&2	
٧o.	Activities	A2		В	טי							
6	Internal C.I. & vertical C.I.		80%	80%	100%	85%	100%	30%		90%		
(i)	Ground Floor Internal C.I. & vertical C.I.	- 000/	100%	100%	100%	100%	100%	100%	100%	95%		
(ii)	Ist floor Internal C.I. & vertical C.I.	90%		100%	100%	100%	100%	100%	100%	95%		
(iii)	IInd floor Internal C.I. & vertical C.I.	90%	100%		100%	100%	100%	100%	100%			
(iv)	IIIrd floor Internal C.I. & vertical C.I.	90%	100%	100%	100%	100%	100%	100%	100%			
(v)	IVth floor Internal C.I. & vertical C.I.	90%	100%	100%		100%	100%	100%	100%	TO MAKE		
(vi)	Vth floor Internal C.I. & vertical C.I.	90%	100%	100%	100%		100%	100%	100%			
(vii)	VIth floor Internal C.I. & vertical C.I.	90%	100%	100%	100%	100%	100%	100%	100%			
(viii)	VIIth floor Internal C.I. & vertical C.I.	90%	100%	100%	100%	100%		100%	100%			
(ix)	VIIIth floor Internal C.I. & vertical C.I.	90%	100%	100%	100%	100%	100%		100%			
(x)	IXth floor Internal C.I. & vertical C.I.	90%	100%	100%	100%	100%	100%	100%			70 X X X	
(xi)	Xth floor Internal C.I. & vertical C.I.	90%	100%	100%	100%	100%	100%	100%	100%	•		
(xii)	XIth floor Internal C.I. & vertical C.I.	90%	100%	100%	100%	100%	100%	100%	100%			
(xiii)	XIIth floor Internal C.I. & vertical C.I.	90%	100%	100%	100%	100%	100%	100%	100%			
(xiv)	XIIIth floor Internal C.I. & vertical C.I.		100%	X	100%	100%	100%	Х	X	•		
,	a. /a la fau bloaka		100%	100%	100%	100%	100%	75%	10%	90%	50%	
6(a												
1	Rain Water Pipe		100%	80%	100%	100%	100%	80%	-	100%		
(i)	Ground Floor Vertical RWP	100%	100%	100%	100%	100%	100%	100%	100%	100%		
(ii)	Ist Floor Vertical RWP	100%	100%	100%	100%	100%	100%	100%	100%	100%		1 1 2 2 2
(iii)	IInd Floor Vertical RWP	100%	100%	100%	100%	100%	100%	100%	100%			the area of the
(iv)	IIIrd Floor Vertical RWP	100%	100%	100%	100%	100%	100%	100%	100%			
(v)	IVth Floor Vertical RWP	100%	100%	100%	100%	100%	100%	100%	100%			W 20 100 100 100 100 100 100 100 100 100
(vi)	VthFloor Vertical RWP		100%	100%	100%	100%	100%	100%	100%			
(vii)	VIth Floor Vertical RWP	100%	100%	100%	100%	100%	100%	100%	100%			
(viii		100%		100%	100%	100%	100%	100%	100%			
(ix)	VIIIth Floor Vertical RWP	100%	100%		100%	100%	100%	100%	100%			
(x)	IXth Floor Vertical RWP	100%	100%	100%		100%	100%	100%	100%			
(xi)	Xth Floor Vertical RWP	100%	100%	100%	100%		100%	100%	100%		De Maria	
(xii	XIth Floor Vertical RWP	100%	100%	100%	100%	100%	1777	100%	100%	1 22 54		
(xii	) XIIth Floor Vertical RWP	100%	100%	100%	100%	100%	100%		X	1 100		
(xiv	/	X	100%	X	100%	100%	100%	X		1		

For MIS C.M. Safta & ASS.

Farman timen girls Single Live Committee Committe

For Kamwerii Const. Co.

Sr.		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII	Community	Guard Room	Remarks
lo.	Activities	A2	B5	В6	B7	C4	C5	D3	D4	Centre	1&2	Hemanie
8	Wooden Door frame fixing	95%	100%	98%	100%	100%	100%	100%	95%	100%	100%	
9	Internal Plaster											
i) .	Ground Floor Internal Plaster	25%	80%	100%	95%	90%	100%	95%	65%	40%	95%	
ii)	Ist floor Internal Plaster	85%	100%	100%	100%	100%	100%	95%	95%	95%		
ii)	IInd floor Internal Plaster	95%	100%	100%	100%	100%	100%	95%	95%	95%		
v)	IIIrd floor Internal Plaster	95%	100%	100%	100%	100%	100%	95%	95%			
v)	IVth floor Internal Plaster	95%	100%	100%	100%	100%	100%	95%	95%			
vi)	Vth floor Internal Plaster	95%	100%	100%	100%	100%	100%	95%	95%		(356-1)	
vii)	VIth floor Internal Plaster	95%	100%	95%	95%	95%	100%	95%	95%	•		
viii)	VIIth floor Internal Plaster	95%	100%	100%	100%	100%	100%	95%	95%			
ix)	VIIIth floor Internal Plaster	95%	100%	100%	100%	100%	100%	95%	95%			
x)	IXth floor Internal Plaster	95%	100%	100%	100%	100%	100%	95%	95%			
xi)	Xth floor Internal Plaster	95%	100%	100%	100%	100%	100%	95%	95%	J 1 1 2 1 5		
xii)	XIth floor Internal Plaster	95%	100%	100%	100%	100%	100%	95%	95%			
xiii)	XIIth floor Internal Plaster	95%	100%	100%	100%	100%	100%	95%	95%	- 1		
xiv)	XIIIth floor Internal Plaster	X	100%	Х	100%	100%	100%	Х	Х	,79		
10	D.B. Fixing											
i)	Ground Floor D.B. Fixing	25%	80%	80%	100%	70%	100%	100%	50%	100%	100%	, 40s
ii)	Ist Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	100%		
iii)	IInd Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	100%		
iv)	IIIrd Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	* 5 • 1.2		8 7 8
v)	IVth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	1.1.1.1.1		
vi)	Vth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	1 - 1		201
vii)	VIth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%			
viii)	VIIth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%			97
ix)	VIIIth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%			
x)	IXth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%			
xi)	Xth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%	•		
xii)	XIth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%			
xiii)	XIIth Floor D.B. Fixing	100%	100%	100%	100%	100%	100%	100%	100%			
(xiv)	XIIIth Floor D.B. Fixing	X	100%	X	100%	100%	100%	X	X	•	*	2 T 4 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1

For MIC C.M. South of Ass Commentation of Single For Kanwage Const. Co. Children C.M. Signature

(SE C.VII)

Auth. Signature

Sr.		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII		Guard Room	Remarks
	Activities	A2	B5	В6	B7	C4	C5	D3	D4	Centre	1&2	
11	A.C.Box Fixing		far Live		5-4		The second	A. Xepl				
		25%	80%	80%	100%	70%	100%	100%	50%	100%		
i)	Ground floor A.C.box fixing	100%	100%	100%	100%	100%	100%	100%	100%	100%		
ii)	Ist Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	100%		
iii)	IInd Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%			, 1875 a 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
iv)	IIIrd Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	•		
v)	IVth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%			The state of the s
vi)	Vth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%	•		
vii)	VIth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%			
viii)	VIIth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%			
(ix)	VIIIth Floor A.C. box Fixing		100%	100%	100%	100%	100%	100%	100%			а —
(x)	IXth Floor A.C. box Fixing	100%		100%	100%	100%	100%	100%	100%			
(xi)	Xth Floor A.C. box Fixing	100%	100%	100%	100%	100%	100%	100%	100%			
(xii)	XIth Floor A.C. box Fixing	100%	100%		100%	100%	100%	100%	100%	30.00		
(xiii)	XIIth Floor A.C. box Fixing	100%	100%	100%		100%	100%	X	X			
(xiv)	XIIIth Floor A.C. box Fixing	X	100%	Х	100%	100%	10076	<del>- ^</del>				1 5 5A 10 10 10 10 10 10 10 10 10 10 10 10 10
12	MS Railing for Balcony & stair case				1000/	4000/	100%	100%	100%	100%		
(i)	MS Railing for Balcony & stair case	100%	100%	100%	100%	100%	100%	10076	10070	10070		
13	Sunken Water Proofing					1000/	4000/	100%	100%	95%		9
(i)	Sunken Water Proofing 1st Floor	90%	100%	100%	100%	100%	100%	100%	100%	60%		
(ii)	Sunken Water Proofing 2nd Floor	90%	100%	100%	100%	100%	100%		100%	- 0070		7.
(iii)	Sunken Water Proofing 3rd Floor	90%	100%	100%	100%	100%	100%	100%	100%			
(iv)	Sunken Water Proofing 4th Floor	90%	100%	100%	100%	100%	100%	100%	100%			
(v)	Sunken Water Proofing 5th Floor	90%	100%	100%	100%	100%	100%	100%				
(vi)	Sunken Water Proofing 6th Floor	90%	100%	100%	100%	100%	100%	100%	100%			
(vii)	Sunken Water Proofing 7th Floor	90%	100%	100%	100%	100%	100%	100%	100%	•		
(viii)	Sunken Water Proofing 8th Floor	90%	100%	100%	100%	100%	100%	100%	100%			
(ix)	Sunken Water Proofing 9th Floor	90%	100%	100%	100%	100%	100%	100%	100%	-		
(x)	Sunken Water Proofing 10th Floor	90%	100%	100%	100%	100%	100%	100%	100%			
(xi)	Sunken Water Proofing 11th Floor	90%	100%	100%	100%	100%	100%	100%	100%	-		
(xii)	Sunken Water Proofing 12th Floor	95%	100%	100%	100%	100%	100%	100%	100%			
(XII)	Sunken Water Proofing 13th Floor	X	100%	X	100%	100%	100%	X	X	•		

For M/S C.M. Cafref A88.

famous famous one Sightor Kanwarji Const. Co.

(wide Civil)

Auth. Signator

Sr.		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII	Community	Guard Room	
No.	Activities	A2	B5	В6	B7	C4	C5	D3	D4	Centre	1&2	Remarks
14	Internal Flat Wiring		95%	85%	35%	90%	95%					
14a	Sheets & Switches Fixing		95%	85%		30%	90%					
15	Supply & Commissioning of Lift		95%		85%	95%	95%					
16	Glazed Tiles Fixing											
(i)	Glazed Tiles Fixing Ground Floor		60%				100%					
(ii)	Glazed Tiles Fixing 1st Floor	35%	100%	95%	95%	95%	100%	70%	50%			
iii)	Glazed Tiles Fixing 2nd Floor	35%	100%	95%	100%	100%	100%	95%	90%		100000000000000000000000000000000000000	
iv)	Glazed Tiles Fixing 3rd Floor	35%	100%	95%	100%	100%	100%	95%	90%			
v)	Glazed Tiles Fixing 4th Floor	35%	100%	95%	100%	100%	100%	95%	95%			
vi)	Glazed Tiles Fixing 5th Floor	35%	100%	95%	100%	100%	100%	95%	95%	7		
vii)	Glazed Tiles Fixing 6th Floor	35%	100%	95%	100%	100%	100%	95%	95%			
viii)	Glazed Tiles Fixing 7th Floor	35%	100%	95%	100%	100%	100%	95%	95%			
ix)	Glazed Tiles Fixing 8th Floor	35%	100%	95%	100%	100%	100%	95%	95%			
x)	Glazed Tiles Fixing 9th Floor	35%	100%	95%	100%	100%	100%	95%	95%			er i Grand de la composition della composition d
xi)	Glazed Tiles Fixing 10th Floor		100%	95%	100%	100%	100%	95%	95%			
xii)	Glazed Tiles Fixing 11th Floor	***	100%	95%	100%	100%	100%	95%	90%			1000
xiii)	Glazed Tiles Fixing 12th Floor		100%	95%	100%	100%	100%	95%	90%			
xiv)	Glazed Tiles Fixing 13th Floor		100%	Х	100%	100%	100%	X	X	•		
17	Kota Stone Fixing		2 Pag			2 2 2						
)	Kota Stone Fixing Ground Floor	-	95%	95%		95%	95%		3-14-1			
i)	Kota Stone Fixing Ist Floor	85%	95%	95%	95%	95%	95%	95%				
ii)	Kota Stone Fixing 2nd Floor	85%	95%	95%	95%	95%	95%	95%				
v)	Kota Stone Fixing 3rd Floor	85%	95%	95%	95%	95%	95%	95%				
v) .	Kota Stone Fixing 4th Floor	85%	95%	95%	95%	95%	95%	95%				
/i)	Kota Stone Fixing 5th Floor	85%	95%	95%	95%	95%	95%	95%				
vii)	Kota Stone Fixing 6th Floor	85%	95%	95%	95%	95%	95%	95%				
viii)	Kota Stone Fixing 7th Floor	85%	95%	95%	95%	95%	95%	95%				
x)	Kota Stone Fixing 8th Floor	85%	95%	95%	95%	95%	95%	95%				
()	Kota Stone Fixing 9th Floor	85%	95%	95%	95%	95%	95%	95%				
(i) -	Kota Stone Fixing 10th Floor	85%	95%	95%	95%	95%	95%	95%				- No.
	Kota Stone Fixing 11th Floor	85%	95%	95%	95%	95%	95%	95%		- 1		
100	Kota Stone Fixing 12th Floor	85%	95%	95%	95%	95%	95%	95%				
xiv)	Kota Stone Fixing 13th Floor	X	95%	X	95%	95%	95%	X	Х			

For MS C.M. Saport Als.

For Kanwarji Const. Co.

Carrier Sing Const. Co.

Carrier Sing Const. Co.

Carrier Sing Const. Co.

Sr.		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII		Community	Guard Room	Remarks
lo.	Activities	A2	B5	B6	B7	C4	C5	D3	D4	Centre	1&2	
18	Kitchen Counter Fixing			4,	0 1 5 E S					•		
i)	Kitchen Counter Fixing Ground Floor		80%	80%	-	30%	100%	80%	•	• 1		
ii)	Kitchen Counter Fixing Ist Floor	95%	100%	95%	95%	100%	100%	95%	95%	•		
iii)	Kitchen Counter Fixing 2nd Floor	95%	100%	95%	95%	100%	100%	95%	95%			
iv)	Kitchen Counter Fixing 3rd Floor	95%	100%	95%	95%	100%	100%	95%	95%	1 1 1		
v)	Kitchen Counter Fixing 4th Floor	95%	100%	95%	95%	100%	100%	95%	95%	- ·		
vi)	Kitchen Counter Fixing 5th Floor	95%	100%	95%	95%	100%	100%	95%	95%	• • • • •		
vii)	Kitchen Counter Fixing 6th Floor	95%	100%	95%	95%	100%	100%	95%	95%	•		
viii)	Kitchen Counter Fixing 7th Floor	95%	100%	95%	95%	100%	100%	95%	95%	5.0		
ix)	Kitchen Counter Fixing 8th Floor	95%	100%	95%	95%	100%	100%	95%	95%		4 2 2 4	
	Kitchen Counter Fixing 9th Floor	95%	100%	95%	95%	100%	100%	95%	95%	S. S.		
x) xi)	Kitchen Counter Fixing 10th Floor	95%	100%	95%	95%	100%	100%	95%	95%			
	Kitchen Counter Fixing 11th Floor	95%	100%	95%	95%	100%	100%	95%	95%			
xii)		95%	100%	95%	95%	100%	100%	95%	95%			
(xiii)	Kitchen Counter Fixing 12th Floor	X	100%	X	95%	100%	100%	X	X			
(xiv)	Kitchen Counter Fixing 13th Floor		10070	7	7,74							
19	Vetrified/Ceramic Tile Fixing		80%		-		95%					
(i)	vetrified/ceramic tile Fixing Ground Floor	15%	100%	80%	95%	95%	100%	75%	40%	- T		
(ii)	vetrified/ceramic tile Fixing 1st Floor	20%	100%	95%	95%	95%	100%	90%	65%			
iii) .	vetrified/ceramic tile Fixing 2nd Floor	20%	100%	95%	95%	95%	100%	90%	65%			
(iv)	vetrified/ceramic tile Fixing 3rd Floor	20%	100%	95%	95%	95%	100%	90%	65%			
(v)	vetrified/ceramic tile Fixing 4th Floor	20%	100%	95%	95%	95%	100%	90%	65%			
(vi)	vetrified/ceramic tile Fixing 5th Floor	20%	100%	95%	95%	95%	100%	90%	50%			
(vii)	vetrified/ceramic tile Fixing 6th Floor	20%	100%	95%	95%	95%	100%	90%	65%			
(viii)	vetrified/ceramic tile Fixing 7th Floor	40%	100%	95%	95%	95%	100%	90%	65%			1
(ix)	vetrified/ceramic tile Fixing 8th Floor	1 1000	100%	95%	95%	95%	100%	90%	65%			
(x)	vetrified/ceramic tile Fixing 9th Floor	40%	10.000	95%	95%	95%	100%	90%	65%	-		
(xi)	vetrified/ceramic tile Fixing 10th Floor	40%	100%		95%	95%	100%	90%	50%	-		
(xii)	vetrified/ceramic tile Fixing 11th Floor	40%	100%	95%		95%	100%	90%	50%		22.5	
(xiii)	vetrified/ceramic tile Fixing 12th Floor	40%	100%	95%	95%		100%	30 76 X	X			9-2-98
(xiv)	vetrified/ceramic tile Fixing 13th Floor	X	100%	X	95%	95%	100%	^	^			19 2 - 1 AM - 2 A

For MI CM Sapra & All

For Kanwayii Const. C

Auth. Sir

Sr.		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII	Community	Guard Room	Remarks
0.	Activities	A2	B5	B6	B7	C4	C5	D3	D4	Centre	1&2	Kemarks
20	Flush Door Fixing & Security Door		× 41 - 15	e la					e a company			
	Flush Door Fixing Ground Floor	hal-	70%				95%					
)	Flush Door Fixing 1st Floor	15%	95%	80%	95%	95%	95%	15%				
i)	Flush Door Fixing 2nd Floor	15%	95%	95%	95%	95%	95%	75%				
v)	Flush Door Fixing 3rd Floor	15%	95%	95%	95%	95%	95%	75%	13.5			
)	Flush Door Fixing 4th Floor	15%	95%	95%	95%	95%	95%	75%				
i)	Flush Door Fixing 5th Floor	15%	95%	95%	95%	95%	95%	75%				
ii)	Flush Door Fixing 6th Floor	15%	80%	80%	90%	80%	95%	60%		7.2		
iii)	Flush Door Fixing 7th Floor	15%	95%	95%	95%	95%	95%	75%				
()	Flush Door Fixing 8th Floor	15%	95%	95%	95%	95%	95%	75%	<del> </del>	· .		
)	Flush Door Fixing 9th Floor		95%	80%	95%	95%	95%	75%				
i)	Flush Door Fixing 10th Floor		95%	80%	95%	95%	95%	60%				
ii)	Flush Door Fixing 11th Floor		95%	80%	95%	95%	95%	60%				
iii)	Flush Door Fixing 12th Floor		95%	80%	95%	95%	95%	75%				
iv)	Flush Door Fixing 13th Floor		95%	X	95%	95%	95%	X	X			
(V)	Aluminium window frame shutter,	•	9070	^	9076	9370	90 /0		^			
21	M.S.Grill & glass											
	Aluminium Window frame shutter, M.S.Grill & Glass		artiger in a	1 6 00 T					Carlo Maria			
	Fixing Ground Floor			• • • • •		•		• 1		•		
)	Aluminium Window frame shutter, M.S.Grill & Glass Fixing 1st floor		95%	80%	85%	85%	95%	55%	25%			
i)	Aluminium Window frame shutter, M.S.Grill & Glass Fixing 2nd Floor		95%	80%	90%	95%	95%	55%	25%			
·)	Aluminium Window frame shutter, M.S.Grill & Glass Fixing 3rd Floor		95%	90%	90%	95%	95%	55%	25%	₩.		
)	Aluminium Window frame shutter, M.S.Grill & Glass Fixing 4th Floor		95%	95%	90%	95%	95%	55%	25%			
	Aluminium Window frame shutter, M.S.Grill & Glass						1.6.1	1 2 2				
i)	Fixing 5thFloor  Aluminium Window frame shutter, M.S.Grill & Glass	-	95%	90%	90%	95%	95%	55%	25%	•		
ii)	Fixing 6th Floor	-	95%	90%	90%	95%	95%	55%	25%	-	A	
ii)	Aluminium Window frame shutter, M.S.Grill & Glass Fixing 7th Floor		95%	90%	90%	95%	95%	55%	25%	-		
)	Aluminium Window frame shutter, M.S.Grill & Glass Fixing 8th Floor		95%	90%	90%	95%	95%	55%	25%			
_	Aluminium Window frame shutter, M.S.Grill & Glass Fixing 9th Floor		95%	90%	90%	95%	95%	55%	25%	Ī		
)	Aluminium Window frame shutter, M.S.Grill & Glass		90%	90%	90%	9070	9070	3376	2070			
)	Fixing 10th Floor Aluminium Window frame shutter, M.S.Grill & Glass		95%	95%	90%	95%	95%	55%	25%			
ii)	Fixing 11th Floor  Aluminium Window frame shutter, M.S.Grill & Glass		95%	95%	90%	95%	95%	55%	25%	-		
ii)	Fixing 12th Floor		95%	95%	90%	95%	95%	55%	25%			
v)	Aluminium Window frame shutter, M.S.Grill & Glass Fixing 13th Floor	<u>~</u>	95%	Χ	90%	95%	95%	х	Χ	0	Ear Kanwa	

for MIS CM. Safre f ASR For Kanwarji Const famous from Conference (with Ciril) Plauth. Sig

Sr.		TW-XIII	TW-XV	TW-XI	TW-XII	TW-XVI	TW-XIV	TW-XVII	TW-XVIII	Community	Guard Room	
No.	Activities	A2	B5	B6	В7	C4	C5	D3	D4	Centre	1&2	Remarks
22	Internal Painting including Wall Putty ,OBD & Enamal Paint											
(i)	Internal Painting including Wall Putty,OBD&Enamal Paint Ground Floor		25%				25%					
ii)	Internal Painting including Wall Putty,OBD & Enamal Paint 1st Floor		75%	-		40%	75%					
iii)	Internal Painting including Wall Putty,OBD & Enamal Paint 2nd Floor		75%			75%	75%					
iv)	Internal Painting including Wall Putty,OBD & Enamal Paint 3rd Floor		75%	•	_	75%	75%					
v)	Internal Painting including Wall Putty,OBD & Enamal Paint 4th Floor		75%	-		75%	75%		2			
vi)	Internal Painting including Wall Putty,OBD & Enamal Paint 5th Floor	-	75%			75%	75%	٠.				
/ii)	Internal Painting including Wall Putty,OBD & Enamal Paint 6th Floor		75%	•		60%	75%		1 > 1() -			
/iii)	Internal Painting including Wall Putty,OBD & Enamal Paint 7th Floor		75%			75%	75%					
<b>(</b> )	Internal Painting including Wall Putty,OBD & Enamal Paint 8th Floor		75%		•	75%	75%		-			
()	Internal Painting including Wall Putty,OBD & Enamal Paint 9th Floor	-	75%			75%	75%		-			
i)	Internal Painting including Wall Putty,OBD & Enamal Paint 10th Floor Internal Painting including Wall Putty,OBD &	-	75%	-		75%	75%	-				
	Enamal Paint 11th Floor  Internal Painting including Wall Putty,OBD &	•	75%	•		75%	75%	-				
	Enamal Paint 12th Floor  Internal Painting including Wall Putty,OBD &		75%			75%	75%					
iv)	Enamal Paint 13th Floor	Х	75%	Х	- 1	75%	75%	Х	<b>X</b> 9		<u> </u>	
23	Flush Door Hardware Fitting			·	8 ,4 1,13					•		
	Flush Door Hardware Fitting Ground Floor Flush Door Hardware Fitting 1st Floor	•		-	2 3 <b>-</b> 7 2 3	200/	- 000/		•	•		
	Flush Door Hardware Fitting 2nd Floor	-	80%			30%	95%		•			<del></del>
	Flush Door Hardware Fitting 3rd Floor		80%				95%		-	•		
	Flush Door Hardware Fitting 4th Floor		80%				95%	•				
	Flush Door Hardware Fitting 5th Floor		80%				95%					
)	Flush Door Hardware Fitting 6th Floor		80%				80%					
ii)	Flush Door Hardware Fitting 7th Floor		80%				95%					
)	Flush Door Hardware Fitting 8th Floor		80%	1	771.35		95%			0		
	Flush Door Hardware Fitting 9th Floor		80%	- 33- 53			95%			.()		
)	Flush Door Hardware Fitting 10th Floor		80%	11 (2) (3)			95%	e Dae		and	For Kanu	orii Const.

For MIS CM Safora T AST, Framan Farman Churchen

(ii)	Flush Door Hardware Fitting 11th Floor		80%				95%					
	Flush Door Hardware Fitting 12th Floor		75%				95%					
(iii)	Flush Door Hardware Fitting 12th Floor	X	75%	Х			75%	Χ	Χ	•		
iv)	Flush Door Hardware Fluing 13th Floor			Transaction		T. THE THE		. 4 7 7				
24	Fire Fighting works for blocks									• 17.7		
<i>(</i> 2)	vertical riser to blocks	100%	100%	100%	100%	100%	100%	100%	100%	100%		
(i)	Hose reel drums without reel	100%	100%	100%	100%	100%	100%	100%	100%	100%		
5 7/	Fire cabinets		85%	85%		85%	85%			•		
· /	fire fighting fixtures	•					13 0	-	• • •		**************************************	
25	Brick Bat Koba At Terrace		100%	100%	100%	100%	100%	45%	95%	•	•	
26	External Plaster	70%	98%	95%	98%	98%	98%	90%	75%	95%	95%	
27	ATT	25%	95%	80%	95%	80%	100%	100%	80%			
28	External Primer		95%			10%	95%	•			•	

Note: Out of 615DUs slabs of 615DUs cast.

For MIS C.M. Safrant Des Curden Sing Farman terman J.E (Civil)

For Kanwarji Const. Co.

Auth. Signatory

s <sup>1</sup> s	External Works a	s on Dated 30-04-2016	
s.no.	Activity	Status of %age	Remarks
1	Boundary wall Works - Brick Work, Plaster, Grill & Painting	95%	
2	Fire water supply line	90%	
3	Fire Ring main & connection for blocks	80%	
4	Water works (L.A.)	90%	
5	Storm /sewerage works (outer ring)	90%	
6	External Electrical - H.T.Room		90% H.T Room
6(a)	External Electrical -Sub Station Foundation	30%	
7	Road work (WBM Ist layer)	50%	
7(a)	Road work (WBM 2nd layer)	25%	
8	Kerb Stone Work	50%	
9	Harvesting Pit	92%	
10	Open Car Parking WBM	48%	
11	Open Car Parking C.C	48%	

For MIS CM Saftre & Ase and Sing For Kanylarii Const. Co forman timen (wide Pil) For Kanylarii Const. Co

## COVD. CAR PARKING AS ON DATED 30-04-2016

s.no.	ACTIVITIES	P1	P2	Р3	P4	P5	P6	P7	P8	Р9	P11	P13	Total parking
1	Numbers of Parking	16	24	6	4	12	18	16	6	28	16	12	158
2	Excavation in Foundation/PCC	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
3	RCC in Footing	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
4	RCC in Plinth Beam	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
5	RCC in Column	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
6	RCC in Roof Slab	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
7	Brick Work	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	100%	
8	Plaster	100%	100%	100%	100%	100%	55%	100%	100%	100%	100%	100%	
9	Flooring	100%	100%	100%	100%	100%	55%	100%	100%	100%	100%	100%	
10	Painting	-		_	,	_	_				-	_	

For M/S C. M. Safraf Ass

Curden Sign Const. Co.

J.E. Civil For Kany Const. Co.

Auth. Signator